

SERVICE LETTER



November 1, 2024

SL2024-1

TITLE

B-5517 BETA ROD ALTERNATIVE

TO:

FAA-Approved Propeller Repair Stations, Aircraft Manufacturers, Owners and Operators

MODELS AFFECTED

All with McCauley Propellers listed in the table below:

3GFR34C701	3GFR34C703	4HFR34C763	4HFR34C764
4HFR34C766	4HFR34C774		

REFERENCE PUBLICATION

MPC700, MODEL C700 SERIES PROPELLER OVERHAUL MANUAL

MPC750, MODEL C750 SERIES PROPELLER OVERHAUL MANUAL

REASON

To provide an alternative option for B-5517 Beta Rod Assembly.

DESCRIPTION

In lieu of replacing the A-1636-35 crush washer and C-5503 Beta Rod for the B-5517 Beta Rod Assembly, McCauley has approved the C-8317 Beta Rod Assembly as an alternative part substitution.

November 1, 2024

Page 1 of 1

TO OBTAIN SATISFACTORY RESULTS, PROCEDURES SPECIFIED IN THIS SERVICE INFORMATION MUST BE ACCOMPLISHED IN ACCORDANCE WITH ACCEPTED METHODS AND PREVAILING GOVERNMENT REGULATIONS. MCCAULEY PROPELLER SYSTEMS CANNOT BE RESPONSIBLE FOR THE QUALITY OF WORK PERFORMED IN ACCOMPLISHING THIS SERVICE INFORMATION.

McCauley Propeller Systems
PO Box 7704
Wichita, Kansas 67277-7704

COPYRIGHT © 2024 McCauley Propeller Systems

