

SERVICE LETTER



November 1, 2024

SL2024-2

TITLE

C-4044 ADAPTER PLATE ALTERNATIVE

TO:

FAA-Approved Propeller Repair Stations, Aircraft Manufacturers, Owners and Operators

MODELS AFFECTED

All with McCauley Propellers listed in the table below:

2A37C223	B2A37C228		
----------	-----------	--	--

REFERENCE PUBLICATION

MPC200, MODEL C200 SERIES PROPELLER OVERHAUL MANUAL

REASON

To provide an alternative option for the obsolete C-4044 Adapter Plate.

DESCRIPTION

McCauley has approved the D-40004 Slip Ring Plate as an alternative part substitution for the C-4044 Adapter Plate.

November 1, 2024

Page 1 of 1

TO OBTAIN SATISFACTORY RESULTS, PROCEDURES SPECIFIED IN THIS SERVICE INFORMATION MUST BE ACCOMPLISHED IN ACCORDANCE WITH ACCEPTED METHODS AND PREVAILING GOVERNMENT REGULATIONS. MCCAULEY PROPELLER SYSTEMS CANNOT BE RESPONSIBLE FOR THE QUALITY OF WORK PERFORMED IN ACCOMPLISHING THIS SERVICE INFORMATION.

McCauley Propeller Systems
PO Box 7704
Wichita, Kansas 67277-7704

COPYRIGHT © 2024 McCauley Propeller Systems

