

# ACTIVE SERVICE LETTERS

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
1972-1	3/3/1972	PRESSURE LATCH PARTS SUPPORT	C10, C38, C39, C46, C48, C52, C54, C55, C59, C60, C61, C65, C68, C71, C72, C74, C75, C80, C81, C86, C87, C89, C91, C92
1974-2	3/29/1974	NEW PROPELLER MODEL AND AVAILABILITY OF MODIFICATION KIT	C58, C98
1975-3	8/11/1975	DIFFERENCE DATA SHEETS FOR MANUAL 730720	1A101, 1A175, 1C160, 1A200 AND 1A170
1976-5	1/28/1976	REMOVAL OF EXPANSION LOCK PLUGS	ALL 3 BLADE THREADED PROPELLERS
1976-8	6/1/1976	CHANGE IN BLADE ACTUATING LINK ASSEMBLY	ALL 3 BLADE FULL FEATHERING THREADED MODELS
1976-9	6/1/1976	THREE BLADE PROPELLER APPROVED FOR CERTAIN CESSNA A188B AG WAGON AND AG TRUCK AIRCRAFT	C90 CESSNA P/N C161006-0206
1976-11	9/17/1976	OBSOLETE FIXED PITCH PROPELLER MODELS	GCM, HCM, PCM, CTM, AND ATM
1976-19	12/1/1976	OIL FILLED PROPELLER HUBS	C58, C90, C98
1977-1	1/7/1977	SERVICE MANUAL 720415 SUPPLEMENT #1	C58, C90
1977-3	2/15/1977	SERVICE MANUAL 710930 SUPPLEMENT #1	C55, C61, C65, C81
1977-4	2/15/1977	IMPROVED SPRINGS FOR CENTRIFUGAL LATCH MECHANISMS (P/N B-4789)	ALL FULL FEATHERING THREADED MODELS
1977-5	5/11/1977	ADDITIONAL OIL FILLED PROPELLER MODELS SERVICE INFORMATION (ADD TO MANUAL 720415)	C53
1978-1	1/13/1978	CORRECTIONS TO PARTS LIST OF FULL FEATHERING PROPELLER SERVICE MANUAL (710930) (P/N A-1635-75 AND A-1635-76 SCREWS)	C59, C60, C61, C65, C68, C71, C72, C74, C75, C80, C86, C87, C89, C91, C92, C93
1978-2	1/13/1978	OIL FILLED PROPELLERS - NEW PROCEDURES AND AREAS REQUIRING SPECIAL ATTENTION	C53, C55, C58, C61, C65, C81, C90, C98
1979-5	7/25/1979	NEW STUDS FOR LYCOMING HUBS (P/N B-5077)	C8, C9, C11, C16, C53, CT69
1979-10	12/28/1979	ADDITIONS AND CORRECTIONS TO GOVERNOR SPECIFICATION TABLES 1-7, 2-7, 2-10, 2-12, AND 2-18	C290D3/T14, /T15, /T18, /T20, /T22, /T23, "CF""D4/T", "CF""D2/T1, -T5, D3/T1, /T5, DCF""D4/T1, T5, DCF""S""D6/T1, DCF""D7/T1, /T5, DCF""S""D8/T1, DCFUS""D12/T1, T3 AND DCFU""D13/T"
1980-2	2/6/1980	MODIFICATION OF SYNCHROPHASER SLAVE GOVERNOR AND OBSOLESENE OF CERTAIN PARTS	DCF"S290D5-"/T3 AND DCF"S31-D3-"/T1
1980-3A	6/26/1980	NEW MCCAULEY MC-1 SYNCHROPHASER SYSTEM	GOVERNOR DCF"S290D9/T" AND CONTROL BOX B-28000

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
1980-8	6/26/1980	INSPECTION FOR OIL LEAKAGE	DCF""290D7-"/T3, DCF"S290D8-"/T3, DCFS290D7-"/T2, DCFS310D7-"/T5, DCFS310D8-"/T1, DCFUS310D3-"/T1 AND C290D3-"/T15 WITH SPECIFIC SERIAL NUMBERS
1982-3	4/16/1982	GOVERNOR MODIFICATION WHEN COMPLYING WITH CESSNA SINGLE ENGINE SERVICE LETTER SE82-14	C290D3-"/T16, AND C290D3-"/T21
1982-4	6/18/1982	NEW GOVERNOR PARTS	NEW P/N A-1635-84, A-1635-86, A-1635-105 SCREWS, AND B-20765 TOP COVER
1982-6	12/3/1982	SERVICE INFORMATION FOR NEW PROPELLER MODELS	1A170E/JFA7658 AND 1A170E/KFA7563
1983-6	8/24/1983	SERVICE INFORMATION TO OIL FILL ADDITIONAL PROPELLER MODELS	C66, C70, C73, C78
1983-7	11/18/1983	BLADE CENTERLINE DIMENSION	FIXED PITCH
1984-4	3/6/1984	SPINNER FILLET CRACKS	C601, C701
1984-7	11/16/1984	MC-1 SYNCHROPHASER SERVICING	DCFS290D9/T3, AND /T6, DCFUS290D9/T3 AND /T6, DCFTS290D10/T7, DCFTS290D15/T7, DCFTUS290D10/T7, AND DCFUS290D15/T7
1985-1	9/16/1985	AVAILABILITY OF CERTAIN GOVERNOR PARTS	C290D2-"/T", "CF""290D1-"/T" AND "CF""310D1-"/T"
1986-2	4/18/1986	REPAIR PROCEDURES - GOVERNOR TOP COVER	C290D2/T", "CF""290D1/T", AND "CF"310D1/T"
1986-6	10/17/1986	NEW HUBS AND BALANCE PROCEDURES	ALL 3 BLADE THREADED, AND C600 SERIES PROPELLERS
1987-1	4/17/1987	BLADE EROSION TAPE (APPROVED TAPE IS Y-8671 FROM 3M)	C652
1987-3	4/17/1987	GREASE LEAKAGE	ALL GREASE LUBRICATED PROPELLERS
1987-5	11/9/1987	PARTS/PROCEDURES TO OIL FILL C30 PROPELLER	C30
1989-2C	2/15/2002	CRITERIA FOR STATIC BLADE SHAKE AND TWIST OF MCCAULEY PROPELLERS	ALL VARIABLE PITCH PROPELLERS
1989-3	5/22/1989	REUSE OF BALL BEARINGS AND RACES IN MCCAULEY TURBINE PROPELLERS	C600, C650, AND C700 SERIES
1989-4D	7/20/2001	DYNAMIC BALANCE OF MCCAULEY PROPELLERS	ALL PROPELLERS, FIXED PITCH
1989-5A	7/16/1990	ADDITIONAL OIL FILLED CONSTANT SPEED PROPELLERS MODELS	ALL C23, C82 REGARDLESS OF DASH NUMBERS
1990-2A	3/15/1991	OIL FILLED CONSTANT SPEED PROPELLER MODELS	C8, C9, C11, C16, C22, C34, C49, C50, C67, CT69

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
1991-5A	1/5/2004	OIL FILLED CONSTANT SPEED PROPELLER MODELS	ALL OIL FILLED THREADED AND OIL FILLED THREADLESS, NON-TURBINE PROPELLERS
1991-11A	11/22/1993	SPINNER INSTALLATION DECAL	ALL PROPELLERS USING SPINNERS WITH FRONT SUPPORTS
1992-3	1/31/1992	NEW PROPELLER MODELS	1A170/BMS7660
1992-6A	12/29/1994	OIL-FILL INSTRUCTIONS	C52, C54, C59, C60, C71 AND C91
1992-7	8/20/1992	OIL-FILL INSTRUCTIONS	C76, C77, C79, AND C88
1992-9	6/30/1992	FIELD REPLACEMENT OF BETA RODS	C701, C702, C703, C1003
1992-11	9/15/1992	FEEDBACK COLLAR REPAIR	C700 AND C1000 SERIES
1992-15	2/1/1993	RED DYE IN TURBINE ENGINES	C600, C650, C700, AND C1000 SERIES
1993-6A	10/3/2005	ANGLE SPECIFICATIONS	1A175 AND 1B175 PROPELLERS
1993-11A	6/20/1995	ADDITIONAL OIL FILL MODELS	C35, C72, C74, C75, C80, C86, C87, C92, AND C93
1993-13	9/15/1993	ADDITIONAL OIL FILL MODELS	C223
1993-17	1/20/1994	OIL-FILL	C14, C28, C29, C31, C32, AND C33
1993-19	1/20/1994	INSTALLATION OF FEATHERING SPRINGS	C652, C653, C661, C1003
1994-2	1/20/1994	SIGNIFICANCE OF CHANGE LETTERS	ALL PROPELLERS AND GOVERNORS
1994-6A	4/22/1997	NEW GOVERNOR ROLL PIN	GOVERNORS PREVIOUSLY USING A-3150-8 OR A-3150-15 PIN
1994-11A	12/1/1994	CHANGE IN GOVERNORS (GASKETS AND SPACERS)	VARIOUS GOVERNOR MODELS
1994-12B	8/5/1997	NEW TOP COVERS ON GOVERNORS	ALL GOVERNORS
1994-22	12/1/1994	OIL-FILL REQUIREMENT	C38, C39, C48, C68, AND C89
1995-4C	3/13/2013	FIELD INSPECTION OF BLADES	ALL "THREADED" C1 THROUGH C98 PROPELLER MODELS
1995-5A	12/5/2007	OPTIONAL CORROSION PREVENTATIVE FOR PROPELLER BLADES AND PROPELLER HUB BLADE SOCKETS	ALL CONSTANT SPEED PROPELLERS
1995-7	4/25/1995	ANGLES FOR PROPELLER	1A170/FFAXXX
1995-19	12/11/1995	OVERSIZE BEARING RACES (INCORPORATED INTO MANUAL MPC200OM, MPC300, MPC400, MPC500OM, 860201 MPC750)	ALL THREADLESS AND TURBINE MODEL PROPELLERS
1995-20A	6/28/1996	REPAIR PROCEDURES FOR A-20026 IDLER GEAR STUD	GOVERNORS USING A-20026 IDLER GEAR STUD

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
1995-21B	8/5/1997	OBSOLETE PROPELLER MODELS	C1, CA6, C7, C8, C10, C11, C14, C16, C18, C21, C23, C28 to C35, C38, C39, C41, C42, C43, C45, C46, C48, C49, C50, C52, C53, C54, C56, C57, C64, C65, C68, CT69, C71, C72, C74, C77, C79, C80, C86, C87, C89, C91, C92, C93, C202, C206, C208, C301
1995-22	12/20/1995	NEW GOVERNOR MODELS	DC290D1/T[X]
1996-1	3/11/1996	DEICE BRUSH WEAR LIMITS	C653
1996-4A	4/22/1997	BLADE STAMPING ON FIXED PITCH PROPELLERS	FIXED PITCH PROPELLERS
1996-5	6/28/1996	PAINT ON TURBINE FEATHERING SPRINGS	ALL TURBINES EXCEPT C1105
1996-8A	12/16/1996	OBSOLETE BOLT KITS	FIXED PITCH PROPELLERS
1996-12	10/29/1996	OPTIONAL SEALANT	MAGNETIC CONTROL HEAD GOVERNORS
1997-1	1/23/1997	GOVERNOR DATA PLATE	ALL GOVERNOR BODIES WITH IDLER GEAR REPAIR
1997-3A	8/28/2001	NEW FIXED PITCH PROPELLER MODEL	1C235/LFA7570
1997-6B	4/7/2003	TROUBLESHOOTING & CONTINUED OPERATION OF TURBINE PROPELLERS WITH BLADE SEAL LEAKAGE	ALL TURBINES
1998-3A	9/21/1998	NEW B-4862 AND B-5043 DECAL	ALL PROPELLERS EXCEPT FIXED PITCH PROPELLERS
1998-5	1/23/1998	NEW CYLINDER AND FRONT SPACER	ALL THREADED EXCEPT, C1 AND C18, NON-OIL-FILLED PROPELLER MODELS
1998-8B	3/15/2001	TORQUING OF CYLINDER ATTACHING SCREWS	ALL OIL FILLED PISTON PROPELLERS
1998-10	6/5/1998	NEW PILOT SPOOL ASSEMBLY	ALL CONSTANT SPEED AND DAMPENED HEAD CONSTANT GOVERNORS
1998-11B	8/1/2000	NEW PUMP COVER	ALL GOVERNORS
1998-18	6/5/1998	SLIP RING ASSEMBLY REWORK	C652, C653, C661, C663, C664
1998-19	6/5/1998	PROPELLER SPECIFICATIONS INCLUDING NEW M1 PITCH DISTRIBUTION	1A103/TCM6958
1998-22A	12/10/1998	LEAKING OF GOVERNORS FROM PRESSURE RELIEF VALVE	ALL GOVERNOR MODELS
1998-23	9/21/1998	OVERSPEEDING OF PROPELLERS	FIXED PITCH AND ALL PROPELLERS EXCEPT C1101, C1102, C1103, AND C1104
1998-24	9/21/1998	TROUBLESHOOTING OF PISTON POWERED PROPELLERS WITH BLADE SEAL LEAKAGE	ALL C200, C300, C400, AND C500 OIL FILLED PROPELLERS
1998-27B	7/20/2001	INTERCHANGEABILITY OF GOVERNOR BODIES	ALL GOVERNORS

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
1998-28B	8/28/2001	NEW PROPELLER MODEL	1A170E/JHA7660
1998-30	12/10/1998	A-20064 AND B-20769 FLYWEIGHTS	ALL GOVERNOR MODELS
1998-33B	2/11/2000	SOLID STATE DEICE TIMERS	MCCAULEY DEICE TIMERS
1999-2A	3/15/2001	FIELD INSPECTION AND REPAIR OF BLADES	C1101, C1102, C1103, AND C1104
1999-3A	8/1/2000	GOVERNOR SPEEDER SPRING	ALL MCCAULEY GOVERNORS
1999-4	3/1/1999	NEW PROPELLER MODEL	1A135/CRM7057
1999-6	6/21/1999	DE-ICE BOOT RESISTANCE VALUES	ALL PROPELLERS USING MCCAULEY DE-ICE BOOTS
1999-7A	11/4/1999	SERVICE INFORMATION FOR NEW PROPELLER MODEL	1A135/DRM
1999-11	9/7/1999	INSPECTION OF GOVERNOR ROLL PIN	ALL GOVERNORS
2000-4	5/1/2000	INSTALLATION OF PRESSURE RELIEF VALVE	GOVERNORS
2000-5A	8/1/2000	NEW BULKHEADS AND SPINNER ASSEMBLIES (Incorporated in MPC200 and MPC400 Overhaul Manuals	C23, C76, C223, C228, C406, C420, C422, C423, C434
2000-9B	3/15/2001	NEW PRESSURE RELIEF NUT	ALL FEATHERING GOVERNORS
2000-10B	3/19/2003	NEW GOVERNOR SPECIFICATIONS	ALL GOVERNORS
2000-11	8/1/2000	GOVERNOR INSTALLATION WITH BRACKET	ALL GOVERNORS
2000-13A	3/15/2001	GOVERNOR NDI	ALL GOVERNOR MODELS
2000-14	11/20/2000	NEW B-20939 GOVERNOR DECAL	GOVERNORS
2000-18	11/20/2000	ACCUMULATOR	B-20816
2000-19	11/20/2000	NEW B-40183-19 DEICE BOOT	ALL PROPELLER MODELS
2000-21	11/20/2000	SLIP RING REPOTTING	ALL PROPELLER MODELS
2001-1F	12/15/2002	MANUAL REVISION PAGES	FIXED PITCH AND THREADED
2001-3	2/9/2001	NEW TOP COVERS	GOVERNORS
2001-5	3/15/2001	MAGNETIC PARTICLE INSPECTION OF FLYWEIGHTS	GOVERNORS
2001-8	11/1/2001	NEW PROPELLER MODEL	1B235/EFC
2001-9	7/20/2001	NEW GOVERNOR TOP COVER GASKET C-20949	GOVERNORS
2001-10	7/20/2001	NEW GOVERNOR TOP COVER B-20159 AND B-20862	GOVERNORS
2001-20C	7/18/2003	NEW GOVERNOR MODEL	C290D8/T1 and C290D8/T2
2002-10	2/15/2002	MANUAL 890119 REVISION 5	C1000 SERIES

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
2002-11	3/1/2002	REPLACEMENT OF ACCUMULATOR END CAPS	D-20215, D-20215-3, D-20816 (ALL ACCUMULATORS)
2002-12	4/15/2002	ACCUMULATOR MOUNTING BRACKET REPLACEMENT	D-20215, D-20816
2002-13	5/15/2002	FLYWEIGHT PIN INSTALLATION	ALL MCCAULEY GOVERNORS
2002-22	9/15/2002	REWORK OF PROPELLER BLADES AND HUBS FOR INCLUSIONS	1C235/LFA
2002-23	9/15/2002	NEW GOVERNOR TOP COVERS	DCFS290D9/T[X], DCFS290D10/T[X], DCFUS290D9/T[X], DCFTS290D10/T[X], DCFTS290D15/T[X], DCFTUS290D10/T[X], AND DCFTUS290D15/T[X]
2002-24B	9/15/2003	INSPECTION OF BULKHEAD FOR CRACKS	C522 AND C523
2002-25	9/15/2002	GOVERNOR BODY CUP REWORK	C290D3/T[X], C290D4/T[X], C290D6/T[X], C290D8/T[X], AND DC290D1/T[X]
2003-1	2/3/2003	COUNTERWEIGHT FAILURE	C300 SERIES
2003-3	4/15/2003	INCORRECT BLADE STAKING ANGLE	114GCA-0, L114GCA-0, L106LA-0, 90DCA-2, 90DFA-4, 82NEA-5 and 82NEA-5.5
2003-4A	5/19/2003	PISTON ROD ASSEMBLIES MANUFACTURED WITHOUT CADMIUM PLATING	ALL 3-BLADE THREADED FEATHERING MODELS
2003-5	8/11/2003	GOVERNOR SERIAL NUMBER STAMPING	ALL GOVERNORS
2005-1	1/31/2005	ANODIZED GOVERNOR FIELD MAINTENANCE AND CARE	All McCauley Governors
2005-2	4/18/2005	CORRECTED TORQUING PROCEDURE FOR COUNTERWEIGHT BOLTS ON THREADED PROPELLERS	All 2 and 3-Blade Threaded Feathering Models
2005-5	8/8/2005	RED DYE LIFE EXTENSION	SPM
2005-6	9/16/2005	AUTOFEATHER SWITCH REPLACEMENT CESSNA 425 STC SA1491GL	McCauley 4-blade STC No. SA1491GL
2005-7	11/28/2005	VIOLATION OF OPERATING RESTRICTIONS FOR FOUR AND FIVE BLADED TURBINE PROPELLERS	All 4 and 5 blade propellers
2005-10A	1/18/2006	POROUS PHENOLIC BUSHINGS AND REVISED HUB LEAK TEST PROCEDURE	Turbine
2006-5B	7/21/2014	OPTIONAL PROCEDURE FOR INSTALLATION OF DE-ICE BOOT RETAINING STRAPS	C400
2007-5	5/22/2007	PISTON ROD ASSEMBLIES INSTALLED IN C300 AND C500 PROPELLERS	C300, C500
2007-8A	10/2/2007	TURBOPROP PISTON TO CYLINDER O-RINGS	C600, C650, C700, C750, C1000, C1100
2007-11	12/11/2007	NEW REPLACEMENT C-20959 AND C-20964 ALUMINUM PROPELLER GOVERNOR TOP COVERS	All McCauley Governors

<i>SLNO</i>	<i>DATE</i>	<i>SUMMARY</i>	<i>MODELS</i>
2008-2	5/12/2008	CORRECTION OF METRIC EQUIVALENT MEASUREMENT	SPM, C1100
2008-3	7/10/2008	MODEL 1A100 and 1A135 PROPELLER SERVICE INFORMATION UPDATE	1A100 and 1A135
2009-1	9/4/2009	MODEL 1A162/TCD6754 PROPELLER SERVICE INFORMATION UPDATE	1A162
2010-1A	3/22/2010	NEW GOVERNOR MODEL SERVICE INFORMATION UPDATE	C290D3/T53, C290D4/T5, and DCFUS290D10/T8
2010-2	4/7/2010	MODEL D3A34C447 PROPELLER SERVICE INFORMATION UPDATE	D3A34C447
2010-3B	8/15/2011	C-7986 RUBBER GASKET INSTALLATION PROPELLER COMPONENT MAINTENANCE MANUAL REVISION 1	3A32C406, D3A32C409, D3A34C420, 3A34C423, D3A32C425, D3A32C426, D3A36C430, B3D36C431, B3D36C432, B3D36C433, 3A36C434, D3A36C435, D3A36C436, B3D36C442, D3A34C443, D3A34C444, and D3A34C447
2010-5	11/22/2010	McCAULEY SERVICE INFORMATION FOR ALL PROPELLER PRODUCTS	ALL PROPELLER MODELS
2010-6	11/22/2010	PROCEDURES FOR PROPELLER SPACER MODIFICATION AND REMOVAL	1A162
2011-2B	11/16/2011	NEW REPLACEMENT D-7873 PISTON ROD ASSEMBLY	C500
2011-3	6/6/2011	REFERENCE MANUAL MPC-5 SUPERCEDURE	ALL PROPELLER MODELS
2011-4	6/6/2011	CORRECTION OF DIMENSION REQUIREMENTS	BOM
2011-5	7/18/2011	ALTERNATE A-1633-128 BLADE SHANK O-RINGS	C431, C432, C433, C434, C435, and C442 model series propeller
2011-6	9/26/2011	NEW REPLACEMENT D-7930 PISTON ROD ASSEMBLY	C301, C302, C303, C304, C305, C306, C307, C308, and C310
2013-1	3/13/2013	SERVICE INFORMATION FOR MCCAULEY PRODUCTS	All Aluminum Propellers, Governors, and Accumulators.
2014-1H	11/10/2017	PUBLICATION OF REVISED McCAULEY MANUALS	BOM, C200, C300, C400, C500, C600, C650, C700, C750, C1100
2014-2	9/22/2014	PROPELLER HUB STUD PLATING CHANGE	All With Hubs That Use Studs
2016-1	5/16/2016	MODEL E300D1-[X]/T1 ELECTRONIC GOVERNOR SERVICE INFORMATION UPDATE	E300D1-[X]/T1
2016-2	11/10/2017	LOW RPM STOP POST MODIFICATION FOR C-20959 TOP COVER	ALL MCCAULEY GOVERNORS EQUIPPEDWITH C-20959 TOP COVERS