SERVICE LETTER



August 17, 2021 SL2021-3

TITLE

AEROSHELL GREASE 5 ALTERNATIVE

TO:

FAA-Approved Propeller Repair Stations, Aircraft Manufacturers, Owners and Operators

MODELS AFFECTED

All with McCauley Propellers

REFERENCE PUBLICATION

SPM100, McCauley Standard Practices Manual

REASON

To provide a alternative option for Aeroshell Grease 5.

DESCRIPTION

As local supply of Aeroshell Grease 5 may be affected, McCauley has approved Propeller Repair Stations, Aircraft Manufacturers, Owners, and Operators to use Mobil Grease 28, Aeroshell Grease 22/58, or Nyco Grease GN3058 as a substitute.

August 17, 2021 Page 1 of 2

SERVICE LETTER



SL2021-3

CORRECTIVE ACTION

- 1. Substitute Aeroshell Grease 5 (McCauley part number A-1637-3), as necessary with the following grease options:
 - Mobil Grease 28, qualified MIL-PRF-81322, General Purpose Aircraft, McCauley part number A-1637-9.
 - (1) Commercially available, contact Exxon Mobil directly via 1-800-662-4525, or worldwide web @ https://www.exxonmobil.com/en-us/aviation/pds/gl-xx-mobilgrease-28
 - B. Aeroshell Grease 22, qualified MIL-PRF-81322G, General Purpose Aircraft.
 - (1) Commercially available, contact Shell directly via worldwide web @ https://www.shell.com/business-customers/aviation/aeroshell/where-to-buy-aeroshell-lubricants.html
 - C. Aeroshell Grease 58, approved SAE AMS3058 and AIMS 09-06-003, General Airframe Lubricant.
 - (1) Commercially available, contact Shell directly via worldwide web @ https://mww.shell.com/business-customers/aviation/aeroshell/where-to-buy-aeroshell-lubricants.html
 - D. Nyco Grease GN3058, qualified MIL-PRF-32014A, Aircraft and Instrument Grease. Approved SAE AMS3058 and AIMS 09-06-003, General Airframe Lubricant.
 - (1) Commercially available, contact Nyco directly via worldwide web @ https://mww.nyco-group.com/contact-form